

From: [Phillip Winsor](#)
To: [Moore, Gary](#)
Subject: RE: Falcon Refinery
Date: Tuesday, July 09, 2013 7:57:06 AM

Gary;

I just sent the TPH TRRP guidance document. Note there are a couple of the guidance documents that address land use classification, groundwater classification, etc. that would be needed at a 'new' site.

Phillip Winsor, PE
Superfund Section
Remediation Division
TCEQ
Office Phone # (512)239-1054
Facsimile: (512) 239-2450
e-mail: Phillip.Winsor@tceq.texas.gov

From: Moore, Gary [<mailto:Moore.Gary@epa.gov>]
Sent: Monday, July 08, 2013 8:21 PM
To: Phillip Winsor
Subject: Falcon Refinery

Phil:

I need to find out what the cleanup levels would be for a release below the tank bottoms. Since these tanks contained crude oil, I would assume that it would be TPH.

How does TCEQ handle cleanups under tanks that are to be refurbished and put back into use?

Thanks

Gary Moore

Federal On-Scene Coordinator

U.S. EPA Region 6

214-789-1627 cell

214-665-6609 office

moore.gary@epa.gov



9568216